

Good Practice in Specimen Preparation, Specimen Handling & Thickness Measurement

Andrew Gregory, Kevin Lees, Bob Clarke, NPL

June 2013



This Presentation covers:



- General Good Practice
- Specimen Handling and Preparation
- Specimen Size and Thickness Measurement

... giving particular emphasis to RF and Microwave dielectric measurements

Topics: Good Practice in Dielectric Measurements:



- Cleanliness
- Clear Identification of specimens
- Storage of specimens
- Manufacturing and preparation of specimens
- Designing specimens to minimise Uncertainty
- Health and Safety Guidelines – toxic materials
- Disposing of specimens safely

- **Keep good records!**

- **Always measure the temperature – ideally to 0.2°C**

Cleanliness



- Do not touch low-loss specimens – you can contaminate them and increase their loss
 - Ceramic specimens can absorb salts from the skin and their loss may be permanently affected
- Toxic specimens may contaminate you!
- Ensure that measurement cells and systems are clean, both before and after use.
 - Specimens may contaminate other specimens

Moisture



- Some specimens – **especially liquids** – are hygroscopic: they can absorb moisture from the atmosphere
- This may not matter for specimens that are already very lossy but absorption of moisture is to be avoided for medium and low loss materials
- Storing for some days in a jar with drying agents may be necessary if specimens are to be measured dry

Clear Identification



- All specimens must be clearly identifiable to ensure that they do not get mixed up with others
 - It is not always a good idea to mark the specimens themselves as this may contaminate them
 - Marking them on supposedly ‘unimportant’ surfaces may limit the number of systems you can measure them in! For a different measurement system, you may have marked a key surface!
 - It may be helpful to record the batch of material from which each specimen has been cut
- Place specimens in clearly marked containers
 - and only take one specimen out at a time!!

Storage

- Store specimens in dark drawers or cupboards
 - some materials, especially polymers, will degrade when exposed to ultraviolet or visible light.
- Support systems adequately whilst in storage to ensure that they do not warp or fracture
 - polymer specimens are prone to warping over long periods of storage. Placing a weight on them can help to avoid this.



Manufacturing and Preparation - 1.



It is very important to have properly prepared specimens

- The uncertainty of most dielectric measurements depends critically upon one or more specimen dimensions.
 - Surfaces need to be flat, circular or spherical (as appropriate) to high levels of tolerance
 - Specimen thicknesses often have to be known accurately, so opposite faces need to be parallel
- These requirements are often best achieved by machining specimens to the right size and shape by appropriate methods
 - Moulding or sintering specimens to size, without further machining, is often necessary but will generally lead to greater measurement uncertainties caused by specimen imperfections

Manufacturing and Preparation - 2.



It is very important to have properly prepared specimens

- **Machining specimens:**
 - Use low tool speeds for polymers
 - No cutting fluids if possible. If dry machining not possible use deionised water
 - Vacuum chucks offer way of holding specimens without contaminating or distorting them
 - The machines cut be thoroughly cleaned beforehand!
 - For coaxial-line/WG measurements minimise corner chipping (asymmetries can generate propagating higher-order modes)
- **Remove all burrs and projections from specimens (they may prevent the specimen from lying flat on a surface)**
 - If possible use centre-less grinding: this avoids a 'knob' or projection at the centre of a turned specimen

Design specimens to match field geometries



- Be aware of the electromagnetic field geometries in your measurement cells
 - This is particularly important if you have imperfect specimens - e.g. warped specimens or specimens that are smaller than ideal, correct specimen placement can improve measurement accuracy.
 - The effect of chips on specimens can sometimes be reduced by orientating specimens in an optimal way
 - Where possible prepare specimens with 2-3 different thicknesses to improve confidence in measurements.
- In general, place the most imperfect part of the specimen in a part of the measurement cell where the electric (or magnetic) field is the lowest allowable.

Health and Safety



- Follow Health and Safety Guidelines for the materials you are dealing with – especially if they are toxic materials
- Dispose of specimens in accordance with Health and Safety guidelines
- This is especially important for liquids – don't just pour them down the sink!
- If in doubt, consult a safety expert
- **National and International chemical practices should always be recognised and followed**

Low Loss specimens

- Be especially aware of contamination, especially by moisture
- Do not touch low loss specimens
- Store them in clean environments



Liquids

- Avoid contamination in either direction – from or to the liquid
 - Don't underestimate the ease with which solvents can absorb contaminants
 - Re-stopper bottle immediately after use
- Beware of evaporation, it cools liquids – measure the temperature of the **liquid**, not the cell it is in.
- Don't reuse liquids after measurement, at least don't put them back into the bottle containing unused liquid.
- Beware of the **Electrode Polarisation Effect** at low frequencies in conducting liquids – dielectric measurements on them can give the wrong results.

Measurement of Specimen

Size and Thickness


1. Use of Micrometers

- Use calibrated traceable micrometers
- Measure at a number of places across the face of the specimen ... the more uneven it is the more points should be measured.
- Bench-mounted micrometers are to be preferred to hand-held because they present less risk of dropping or contaminating specimens
- Clean the anvils beforehand by drawing a lint free cloth sideways across them
- Ratchet mechanisms can be used for hard specimens
- Soft specimens require minimal force, do not use ratchet mechanisms - feel contact with fingers.
- Rough specimens - bear in mind that micrometers measure the top of projections – the mean thickness will be systematically thinner. Use smaller anvil heads.





EMINDA

Electromagnetic Characterisation of Materials for
Industrial Applications up to Microwave Frequencies



Measurement of Specimen Size and Thickness

2. Diameters – Air-gauging



- In some techniques, e.g. measurement of coaxial specimens in a coaxial transmission line, air gaps can cause large measurement errors. Corrections can be applied if the inner and outer diameters of the specimen (and line) are measured.
- Air-gauging can measure these diameters to about 1 micron.

Measurement of Specimen Size and Thickness

3a. Thin films

Potential Techniques with comparison of costs (in £UK)

This is a very complex topic!

Name	Resolution	Equipment Cost	Upkeep Cost	Time (not including setup)
Bench Micrometer	1 μm	£500	£200 per year recalibration	Seconds
Stylus Profilometre	1 nm	£25,000		A Few Minutes
AFM	Sub-nm	£50,000+		Tens of minutes
Confocal microscopy	10 nm	£15,000+	£3000 per annum	Less than a minute
Ellipsometry	Sub nm	£10,000s+	£200 per 1k hrs use.	Tens of minutes
White light interferometry	$\sim 1 \mu\text{m}$	£5,000+	£3000 per annum	Tens of minutes
SEM	Sub nm	£100,000+	£15k service contract	Half an hour

Measurement of Specimen Size and Thickness

3b. Thin films – some thoughts:

- Specimens of 10 microns and above in thickness: a **bench micrometer** may give sufficient accuracy.
- If the film is available before metallisation, its thickness is below 1 μm and it is transparent at some optical wave length then **ellipsometry** may be recommended due to its low cost and accuracy.
- If ellipsometry is not possible and if metallisation thickness must be measured the preferred option could be **confocal microscopy**, provided the thin films have thicknesses greater than 50 nm.
- If the equipment and expertise is already available , **AFM techniques** would be the preferred measurement for films below 500 nm.

Conclusions

The most important things to remember:

- Cleanliness is important
- Be aware of specimen contamination
- Always measure the specimen temperature
- Specimen dimensions are critical parameters in EM materials measurements:
 - Machine specimens to optimise thicknesses and the necessary tolerances
 - Use the best methods to measure thickness.
- Take care not to mix specimens up
- Health and safety are important: know the risks associated with the materials you are measuring.